

M4NS/M4YS

■ Features

- Loop powered type
- Input : 4~20mAADC
- Max. display : -1999 ~ 9999
- Prescale function
- Decimal point setting function
- Hi / Low limit input correction function
- Display peak value monitoring function
- Change function of peak value monitoring delay time
- Display cycle change function
(Selectable 0.5sec/1sec/2sec/3sec/4sec/5sec)
- Error display function



Please read "Caution for your safety" in operation manual before using.

■ Ordering information

M 4 N S - N A

Input specification

A 4~20mAADC

Power supply

N Loop powered type

Scaling meter

S Scaling meter

Size

N DIN Size W48×H24mm

Y DIN Size W72×H36mm

Digit

4 4 Digit

Item

M Meter

■ Specifications

Model	M4NS-NA	M4YS-NA
Measurement input	4~20mAADC	
Power supply	No voltage type	
Power consumption		
Display method	7Segment LED Display(4digit)	
Character height	9mm	14.2mm
Display accuracy	0.3% full scale of ±1Digit	
Display cycle	Selectable 0.5sec/1sec/2sec/3sec/4sec/5sec	
Resolution	12,000 resolution	
Max. display range	-1999 ~ 9999	
Setting type	Front S/W key	
Max. allowable input	150% of measurement input	
Self-diagnosis function	Error display function(HHHH/LLLL)	
Insulation resistance	Min. 100MΩ (500VDC)	
Dielectric strength	2000VAC for 1minute	
Vibration	Mechanical	0.75mm amplitude at frequency of -10 ~ 55Hz in each of X, Y, Z directions for 1hour
	Malfunction	0.5mm amplitude at frequency of -10 ~ 55Hz in each of X, Y, Z directions for 10minute
Shock	Mechanical	300m/s² (30G) in X, Y, Z directions for 3 times
	Malfunction	100m/s² (10G) in X, Y, Z directions for 3 times
Ambient temperature	-10 ~ 50°C (at non-freezing status)	
Storage temperature	-25 ~ 66°C (at non-freezing status)	
Ambient humidity	35~85%RH	
Weight	Approx. 46g	Approx. 88g

Scaling Meter

Front panel identification


●M4NS-NA



① Display value, Parameter, Error display

② MD Key : When enter into Parameter group, return to RUN mode, After completing Parameter setting.

●M4YS-NA




③ ▲ (Up) key : When enter into the status of Parameter setting


④ ◀ (Move) key : When enter into the status of parameter setting and digit moving

Connections

●M4NS-NA





●M4YS-NA




Dimensions

●M4NS-NA




●Panel cut-out




Unit:mm

●M4YS-NA



●Panel cut-out



Unit:mm

Parameter

Display	Function	Setting range
L-SC	Low Scale	Low limit display value for 4mA input -1.999 ~ 9.999 -19.99 ~ 99.99 -199.9 ~ 999.9 -1999 ~ 9999
H-SC	High Scale	Hi limit display value for 20mA input -1999 ~ 9999
dot	Dot	Set Dot position 0000, 000.0 00.00, 0.000
lnb.L	—	Correct the Low-limit value of display value(%) -100 ~ 100
lnb.H	—	Correct the High-limit value of display value(%) 0.900 ~ 1.100
PEvt	Peak Time	See the peak value monitoring delay time 0 ~ 30sec
d15.t	Display time	Selectable sampling time(sec) Selectable 0.5/1.0/2.0/3.0/4.0/5.0sec
E.Pct	Error %	Display the measurement input is out of input range E.Pct 0, E.Pct 1, E.Pct 2, E.Pct 3, E.Pct 4
LoC	Lock	Set the lock function Selectable ON, OFF

Factory Default setting

Parameter	Parameter display	Factory default
Low limit display value for 4mA input	L-SC	400
Hi limit display value for 20mA input	H-SC	2000
Set Dot position	dot	00.00
Correction of Low limit value input	lnb.L	0000
Correction of Hi limit value input	lnb.H	1000
Peak value monitoring delay time	PEvt	015
Display cycle	d15.t	0.5 5
Set % of HHHH/LLLL display range	E.Pct	3
Lock setting	LoC	OFF

(A) Counter

(B) Timer

(C) Temp. controller

(D) Power controller

(E) Panel meter

(F) Tacho/ Speed/ Pulse meter

(G) Display unit

(H) Sensor controller

(I) Proximity sensor


(J) Photo electric sensor

(K) Pressure sensor


(L) Rotary encoder

(M) 5-Phase stepping motor & Driver & Controller

■ Parameter 0 group(Monitoring mode for Peak display value)



■ Parameter 1 group




*Pressing **[MD]** key to complete the setting and move to next Parameter in status of changing setting value.

*Pressing **[MD]** key for 3 sec. to move to RUN mode after displaying **run**.

*If no key touched for 60sec., it will return to RUN mode.

Scaling Meter


Application of connections



Function


Prescale function [L-SC/H-SC Mode]

This function is to display the value with setting certain Hi/Low limit value against 4–20mADC input. For example if set a=4mADC, b=20mADC and A, B as display value, it will be displayed a=A, b=B.



Decimal point setting function [dot Mode]

This function is to set the decimal point position of display value (Set in Parameter setting group)



Ability to use ▲ (Shift) or ▾ (Up) for moving decimal point.

Correction function [I nb.H / I nb.L Mode]

This function is to adjust the error of display value after calculating scale value for measuring input and also correct the input error of sensor etc.

I nb.L : -100 to 100 [Adjust deviation of Low value],
I nb.H : 0.900 to 1.100 [Correct gradient(%) of High value]

Ex) When display value is 0.0 to 500.0 against 4–20mA input

If the display value is "1.2" for 4mA input, set -12(Ignore the decimal point) as **I nb.L** value to display "0.0" So enable to remove offset of Low display value.

*Correct the high value

When completed above Low value setting then apply 20mA, if the display value is "500.5, the correction value will be 0.999($5005/5000=0.999$), set 0.999 as **I nb.H** value then enable to correct High value ($5000 \times 0.999 = 5000$).

Ignore the decimal point.

Display cycle delay function

It is difficult to display when the measuring input value is fluctuating. In this case it is able to make display value stable by delaying display cycle. Display cycle can be changed in **DIS.t** mode of Parameter 2 (Selectable 0.5s/1.0s/2.0s/3.0s/4.0s/5.0s). If select 5.0s, it will be the measuring input value on an average for 5sec., then display it every 5sec.

Error display function [E.PCt Mode]

Type of error sign

Error code	Error description
E.PCt 0	LLLL / HHHH are displayed when it is over 0% out 4–20mADC range
E.PCt 1	LLLL / HHHH are displayed when it is over 1% out 4–20mADC range
E.PCt 2	LLLL / HHHH are displayed when it is over 2% out 4–20mADC range
E.PCt 3	LLLL / HHHH are displayed when it is over 3% out 4–20mADC range
E.PCt 4	L-SC / H-SC are displayed always when it is out of 4–20mADC range

*Caution: **LLLL / HHHH** will not be displayed when the differences are under 50 between **L-SC** and **H-SC**.

Error display

In case of selection "**E.PCt 3**"

It is the case that input current is lower or higher than 3% in 4–20mADC, therefore, the deviation value of current will be the scale value of measurement input range $(16mA) \times 3\% = 0.48mA$.
 \therefore When input current is lower than $4mA - 0.48mA = 3.52mA$, **LLLL** is displayed. On the contrast, when input current is $20mA + 0.48mA = 20.48mA$, **HHHH** is displayed.

② When it is beyond limit Low scale (**L-SC**) or limit High scale (**H-SC**), the **LLLL** and **HHHH** signals are displayed.

Turn Error display off

LLLL and **HHHH** are displayed when input is out of measuring range, therefore, it will be disappeared automatically when input returns to measuring range.

Display peak value monitoring function

[PEPH / PEPL Mode]

This function is to monitor Max/Min value of display and display that data on **PEPH** mode and **PEPL** mode of parameter setting group.

For Max. value monitoring, set delay time at **PEPH** mode in order to initial overcurrent.

Delay time range is 0~30sec, and start monitoring after setting time.

- (A) Counter
- (B) Timer
- (C) Temp. controller
- (D) Power controller
- (E) Panel meter
- (F) Tacho/ Speed/ Pulse meter
- (G) Display unit
- (H) Sensor controller
- (I) Proximity sensor
- (J) Photo electric sensor
- (K) Pressure sensor
- (L) Rotary encoder
- (M) 5-Phase stepping motor & Driver & Controller